


Summer STEM Academy

6 X 10 HDPE Sign Instructions

Follow these instructions to draw your personalized sign on the CNC router in the Woodshop / Manufacturing shop.

1. Log on to your computer and double click on the “VCarve Pro” icon on the desktop. Your screen should look like the image below.



Use the left mouse button to click on the “Create a new file” icon.

VCarve Pro - ShopBot Edition (Grants Pass High School) - [New]

File Edit Model Toolpaths View Gadgets Help

Drawing **New** 3D View

Job Setup

Job Size (X & Y)

Width (x): 10.0 inches
Height (y): 6.0 inches

Material (Z)

Thickness (z): 0.5 inches

XY Datum Position

☐ Use Offset
X: 0.0
Y: 0.0

Units

☒ inches ☐ mm

Design Scaling

☐ Scale design with job size

Modeling Resolution

Standard (fastest)

Appearance

Blue Plastic
Solid Color:

OK Cancel


Here is where you will set your material dimensions. Click in the "Width" box and enter 10.0

Now click on the "Height" box and enter a value of 6.0


Click in the "Thickness" box and enter 0.5

Make sure that everything else looks like it does here.

Double check everything and make sure your settings match what you see on the left and then click on the "OK" button at the bottom.



Now we are going to enter some text onto your material. Click on the "Text" icon.




You need to type your name (or whatever you would like to see) in the Text box. Use the enter key when entering your text so that every word is on its own line.


Choose a font that you like from the available fonts board.



We are going to use a "Text Height" of 1.0 inch. If your name is too big we will need to make some changes so it will fit.



Now you can click on the "Apply" button, then click on the "Close" button.




Your text is going to be in a weird place so we need to center it on your material. Click on the "Center on Material" button under "Align Objects" to place your text in the middle of the material.












Enter the values shown here then click "Create". As long as your first box looks like the one on the right you can then click on "Close".




We are going to create a second box that is a quarter of an inch smaller than the first one all the way around. This will define the "frame" that we will be cutting. Enter all of the values shown here then click "Create" then "Close".







Before going any further you should save your drawing. Click on the "File" button in the upper left corner of the window then move down and click on the "Save As" option. Save this file on to your desktop or a flash drive, Use your first name and last initial as the filename.




Now we are going to work on generating the toolpaths that will eventually make your sign. Click on the "Switch to Toolpaths" tab.



The toolbar that was on the left before has now been replaced with the "Toolpaths" toolbar on the right. This is where we will generate the "G Code" that will instruct the machine just how to go about cutting out your sign.



Click on one of the two boxes that you created earlier and it should turn red. Once one of them is activated, hold down the "Shift" key and click on the other box. Both of the boxes that define your "Frame" should now be red.



Click on the "Select" button in the "Tool" window.

After you click on the "Select" button, the window below will show up. Find the "End Mill (.0625)" and click on it. Set all of the numbers to exactly what you see here.

Tool Database

Tool List

GPHS Available Bits

Wood

- #1: 1/4" Down-cut (57-91)
- Ball Nose 0.0625 inches Dia
- End Mill (.0625)
- End Mill (0.125 inches)
- V-Bit 90 deg 3/4" dia Freud
- #6: 1/8 End Mill downcut
- #17: 60 Degree V-Bit 1" (
- Fluting Round Nose 0.75 in
- End Mill 3/8" 2 flute upcut
- End Mill (0.125 inches)
- 1/4" Up-cut (52-910)
- 1/8" Tapered Ball Nose (7
- 1/4" upcut super "O" single
- 1/4" Downcut2 flute freud
- 1/2" dia. 2 flute 1 1/2" str
- End Mill (0.375 inches)
- 1 1/4" Spoil-Board Cutter
- 1/2" Straight (48-072)
- 1/4" Straight (48-005)

Our Wood Bits

- End Mill (0.12 inches)
- End Mill (0.06 inches)

Tool Info

Name: End Mill (.0625)

Tool Type: End Mill

Notes:

Geometry

Diameter (D): 0.0625 inches

Cutting Parameters

Pass Depth: 0.0625 inches

Stepover: 0.0156 inches 25.0 %

Feeds and Speeds

Spindle Speed: 14000 r.p.m

Feed Rate: 2.0 inches/sec

Plunge Rate: 2.0 inches/sec

Tool Number: 4

Apply

OK

Cancel

Once you have all of the numbers in the Tool Database the same as you see here, click on the "Apply" button to save all of your settings then click on "OK".

Pocket Toolpath

Tool: End Mill (.0625)

Select...

Edit...

Passes: 2

Edit Passes...

☐ Use Larger Area Clearance Tool

Not using area clear tool

Select...

Edit...

Passes: 0

Edit Passes...

Clear Pocket ...

☒ Offset

☐ Raster



Cut Direction

☐ Climb

☒ Conventional

Raster Angle: 0.0 degrees

Profile Pass: Last

Pocket Allowance: 0.0 inches

☐ Ramp Plunge Moves

Distance: 1.0 inches

☐ Use Vector Selection Order

Safe Z: 0.5 inches

Home Position: X:0.00 Y:0.00 Z:0.80

☐ Project toolpath onto 3D model

Vector Selection: Manual

Selector...

Name: Pocket 1

Calculate

Close

Toolpaths

Pocket Toolpath

Cutting Depths

Start Depth (D) 0.0 inches

Cut Depth (C) 0.125 inches

☒ Show advanced toolpath options

Tool: End Mill (.0625)

Select ... Edit ...

Passes: 2 Edit Passes ...

☐ Use Larger Area Clearance Tool

Not using area clear tool

Select ... Edit ...

Passes: 0 Edit Passes ...

Clear Pocket ...

☒ Offset ☐ Raster

Cut Direction

☐ Climb ☒ Conventional

Raster Angle 0.0 degrees

Profile Pass Last

Pocket Allowance 0.0 inches

☒ Ramp Plunge Moves

Distance 1.0 inches

☐ Use Vector Selection Order

Safe Z 0.5 inches

Home Position X:0.00 Y:0.00 Z:0.80

☐ Project toolpath onto 3D model


Vector Selection: Manual Selector ...



Name: Frame Border

Calculate Close

Once you closed the "Tool Database" window, check that the "Pocket Toolpath" window has the same settings as you see here.

Give the file the name you see here and click on the "Calculate" button.





We are going to follow the same steps as we did to make the frame border. Click on the "Select" button in the tool window.

Tool Database

Tool List

GPHS Available Bits
Wood
#1: 1/4" Down-cut (57-91)
Ball Nose 0.0625 inches Dia
End Mill (.0625)
End Mill (0.125 inches)
V-Bit 90 deg 3/4" dia Freud
#6: 1/8 End Mill downcut
#17: 60 Degree V-Bit 1" (0.125)
Fluting Round Nose 0.75" dia
End Mill 3/8" 2 flute upcut
End Mill (0.125 inches)
1/4" Up-cut (52-910)
1/8" Tapered Ball Nose (7)
1/4" upcut super "O" single
1/4" Downcut2 flute freud
1/2" dia. 2 flute 1 1/2" str
End Mill (0.375 inches)
1 1/4" Spoil-Board Cutter (48-072)
1/2" Straight (48-072)

Tool Info

Name End Mill (.0625)

Tool Type End Mill

Notes

Geometry

Diameter (D) 0.0625 inches

Cutting Parameters

Pass Depth 0.0625 inches

Stepover 0.0156 inches 25.0 %

Feeds and Speeds

Spindle Speed 14000 r.p.m

Feed Rate 2.0 inches/sec

Plunge Rate 2.0 inches/sec

Tool Number 4

Apply

OK

Cancel

The same tool choice window will appear as before. Choose the "End Mill (.0625)" again and check to make sure that all of the parameters are set to what you see here.

Once all of the boxes are the same as what you see here, click on "Apply" then click

Pocket Toolpath

Cutting Depths

Start Depth (D) 0.0 inches

Cut Depth (C) 0.125 inches

☒ Show advanced toolpath options

Tool: End Mill (.0625)

Select ...

Edit ...

Passes: 2

Edit Passes ...

Use Larger Area Clearance Tool

Not using area clear tool

Select ...

Edit ...

Passes: 0

Edit Passes ...

Clear Pocket ...

☒ Offset ☐ Raster

Cut Direction

☐ Climb

☒ Conventional

Raster Angle 0.0 degrees

Profile Pass Last

Pocket Allowance 0.0 inches

Ramp Plunge Moves

☐ Ramp Plunge Moves

Distance 1.0 inches

Use Vector Selection Order

Safe Z 0.5 inches

Home Position X:0.00 Y:0.00 Z:0.80

☐ Project toolpath onto 3D model

Vector Selection: Manual

Selector ...

Name: Pocket 1

Calculate

Close

Toolpaths

Pocket Toolpath

Cutting Depths

Start Depth (D) 0.0 inches

Cut Depth (C) 0.125 inches

☒ Show advanced toolpath options

Tool: End Mill (.0625)

Select ... Edit ...

Passes: 2 Edit Passes ...

☐ Use Larger Area Clearance Tool

Not using area clear tool

Select ... Edit ...

Passes: 0 Edit Passes ...

Clear Pocket ...

☒ Offset ☐ Raster

Cut Direction

☐ Climb ☒ Conventional

Raster Angle 0.0 degrees

Profile Pass Last

Pocket Allowance 0.0 inches

☒ Ramp Plunge Moves

Distance 1.0 inches

☐ Use Vector Selection Order

Safe Z 0.5 inches

Home Position X:0.00 Y:0.00 Z:0.80

☐ Project toolpath onto 3D model


Vector Selection: Manual Selector ...

Name: Name Toolpath

Calculate Close


Everything should look the same as it does here. The only thing you need to do is to give the toolpath a name. Give it your own name so we can find it later when we go out into the shop to cut your sign.

Now you can go ahead and click on the "Calculate" button then click on the "Close" button.




If everything looks good, click on the "Close" button to exit out of this window.

We need to save your toolpaths next so make sure the boxes are checked in the "Toolpath List".




Once you have checked the boxes for each toolpath, click on the "Save Toolpath" icon.


You should see the two toolpaths that you are saving in the window. The Frame VCarve and the Name toolpath.



Make sure that the "Post Processor" information matches what you see here and then click on the "Save Toolpaths to File" button.

Save it to your Desktop
and name it with your
first name, last initial
and the word
"Toolpath", just like
you see here.





Save the file to your Desktop. Give it a name using the format you see here.

